

Model

S/N



LISTED
7Z06

LABORATORY EQUIPMENT



SEE INSTRUCTION MANUAL

Achtung: Vor Öffnen Netzstecker ziehen!

FUSE TYPE: 3AG TYPE T, TIME-LAG
(2 REQUIRED). SEE TABLE FOR
FUSE RATING.

VOLTAGE~	FUSES
100 - 120 V	1/4 A
220 - 240 V	1/8 A

50 - 60 Hz 10 W

Sicherung: 2 x 125 mA träge, 220-240 V

WARNING ELECTRIC SHOCK HAZARD. DO NOT OPEN CASE.
REFER SERVICING TO QUALIFIED PERSONNEL. FOR CONTINUED
PROTECTION AGAINST FIRE HAZARD, REPLACE FUSES ONLY
WITH FUSES OF THE SPECIFIED TYPE AND CURRENT RATING.

WESCOR
Made in USA

459 South Main Street, Logan, Utah 84321 USA

55-0102-01A